



Instruction Manual
K10WBT 10" Enclosed Bench Top
Metallurgical Wet Saw

Kalamazoo Industries, Inc.
6856 E K Ave
Kalamazoo, Michigan
1-800-592-2050
www.kalamazoolnd.com

1. Introduction

Thank you for choosing the Kalamazoo Industries K10WBT 10-Inch Enclosed Bench Top Metallurgical Wet Saw. This industrial-grade wet sectioning machine is designed to deliver efficient, clean cuts of metal samples for metallographic sample preparation and metallurgical analysis.

The K10WBT features a robust 2HP three-phase TEFC motor delivering a spindle speed of 3,450 RPM, a fully enclosed all-steel construction, and a heavy-duty recirculating coolant system with a 6-gallon capacity tank. The wet cutting process minimizes heat damage and preserves sample integrity, making this machine ideal for material inspection, weld testing, and precision sectioning tasks.

Please read this manual thoroughly before operating the equipment. Proper understanding of the machine's features, safety requirements, and maintenance procedures will ensure optimal performance and longevity.

1.1 Intended Use

The K10WBT is specifically designed for wet cutting of ferrous metals and materials for metallurgical analysis, including:

- Low-carbon steel (bar stock, angle iron, flat stock)
- Structural steel and alloys
- Cast iron
- Rebar
- Mild steel pipe
- Weld samples for inspection and testing
- Ceramic materials

2. Safety Information

⚠ WARNING: TO REDUCE THE RISK OF FIRE OR SHOCK HAZARD, DO NOT EXPOSE THIS EQUIPMENT TO RAIN, LIQUID, OR MOISTURE BEYOND THE DESIGNED COOLANT SYSTEM.

Read all safety instructions before operating this equipment. Failure to follow safety guidelines may result in serious injury or death.

2.1 General Safety Precautions

1. Always wear appropriate personal protective equipment (PPE) including safety glasses, hearing protection, and work gloves.
2. Keep the work area clean and well-lit. Cluttered or dark areas invite accidents.
3. Do not operate the saw under the influence of drugs, alcohol, or medication that may impair judgment.
4. Keep bystanders at a safe distance from the operating machine.
5. Never leave the machine running unattended.
6. Ensure the enclosed door is properly closed during operation.
7. Disconnect power before changing wheels or performing maintenance.
8. Securely clamp all workpieces in the vises before cutting.
9. Use only water-soluble coolant with a rust inhibitor in the coolant system.

2.2 Electrical Safety

- Ensure proper grounding of the machine before operation.
- Verify voltage requirements match your facility's electrical supply (230V or 460V three phase).
- Use only qualified electricians for electrical connections and repairs.
- Do not operate with damaged wiring or electrical components.

2.3 Abrasive Wheel Safety

- Use only 10" abrasive cutoff wheels rated for 3,450 RPM or higher.
- Inspect wheels for cracks, damage, or excessive wear before each use.
- Replace damaged or worn wheels immediately.
- Allow the wheel to reach full speed before beginning a cut.
- Select the appropriate wheel type for your specific material.

2.4 Coolant System Safety

- Monitor coolant level regularly during operation. Never operate without adequate coolant.
- Use only recommended water-soluble coolant with rust inhibitor.
- Clean and replace coolant regularly to prevent bacterial growth and maintain cutting performance.
- Ensure coolant nozzles are properly directed at the cutting zone before starting.

3. Technical Specifications

3.1 Motor and Performance

Specification	Value
Motor Power	2 HP TEFC
Phase	3 Phase
Voltage Options	230V or 460V
3PH FLA (230V)	5.2 amps
3PH FLA (460V)	2.6 amps
Pump FLA (115V)	2.4 amps
Spindle Speed	3,450 RPM
Spindle Arbor	5/8" LH (optional: 1.250" or 32mm)
Blade Diameter	10" abrasive cutoff wheel (not included)

3.2 Cutting Capacity

Material Type	Maximum Capacity
Solid Round (Mild Steel)	1-1/2 inches
Pipe (Mild Steel)	2-1/2 inches

3.3 Coolant System

Component	Specification
Pump Type	Heavy-duty recirculating pump
Coolant Tank	Metal, 6-gallon capacity
Coolant Nozzles	Adjustable dual flare nozzles with flow control ball valve
Wash Down	Integrated wash down hose
Recommended Coolant	Water-soluble coolant with rust inhibitor

3.4 Construction

Component	Material/Type
Enclosure	Fully enclosed all-steel construction
Access Panel	Removable 5" left side panel for long parts
Motor Access	Removable rear access panel
Controls	Magnetic controls with 24V on/off push/pull buttons
Lighting	Internal light
Vise System	Two robust replaceable 2-7/16" toolmakers vises
Work Table	T-Slot table
Wheel Guard	Integrated enclosed wheel guard

3.5 Dimensions and Weight

Dimension	Measurement
Shipping Length (without stand)	47 inches
Shipping Width (without stand)	37 inches
Shipping Height (without stand)	40 inches
Shipping Weight (without stand)	500 lbs (crated)
Shipping Length (with stand)	48 inches
Shipping Width (with stand)	37 inches
Shipping Height (with stand)	69 inches
Shipping Weight (with stand)	700 lbs (crated)

Note: Shipping weights and dimensions are subject to change.

4. Features and Components

4.1 Key Features

The K10WBT incorporates several features designed for industrial metallurgical performance and operator convenience:

Fully Enclosed All-Steel Construction

The fully enclosed design contains coolant splash and debris, maintaining a clean work environment while protecting the operator. All-steel construction ensures long-lasting durability and reliability.

Heavy-Duty Recirculating Coolant System

The integrated coolant system features a heavy-duty recirculating pump and a 6-gallon metal coolant tank for continuous wet cutting operation. Adjustable dual coolant flare nozzles with flow control ball valve provide precise coolant delivery to the cutting zone.

Magnetic Controls

Magnetic controls with 24V on/off push/pull buttons provide safe, reliable machine operation. The magnetic starter prevents automatic restart after a power interruption.

Toolmakers Vises

Two robust, replaceable 2-7/16" toolmakers vises provide secure, precise clamping for metallurgical sample preparation.

T-Slot Table

The T-slot work table allows flexible workpiece positioning and accommodates custom fixturing for specialized cutting applications.

Internal Lighting

Built-in internal lighting provides clear visibility of the cutting area through the enclosed viewing window.

Removable Side Access Panel

A removable 5" left side access panel accommodates long parts that extend beyond the enclosure.

Wash Down Hose

An integrated wash down hose simplifies cleaning of the cutting chamber and coolant tank.

4.2 Available Options

- 710-052 Door safety interlocks
- Alternative spindle arbor: 1.25" or 32mm
- Steel Stand (Model 12-WBT): Provides a stable, ergonomic working height

5. Installation and Setup

5.1 Unpacking and Inspection

1. Carefully remove all packing materials and inspect the machine for shipping damage.
2. Verify all components are present according to the packing list.
3. Report any damage or missing items to Kalamazoo Industries immediately.
4. Remove any protective coatings from machined surfaces.

5.2 Location Requirements

- Place the machine on a level, stable surface capable of supporting the machine weight.
- Ensure adequate clearance around all sides for operation, maintenance, and door opening.
- Provide adequate lighting and ventilation.
- Position the machine near a floor drain or use drip trays for coolant management.

5.3 Electrical Connection

CAUTION: Electrical connections must be performed by a qualified electrician in accordance with local electrical codes.

1. Verify the voltage requirements match your facility's power supply (230V or 460V three phase).
2. Connect to an appropriately rated circuit with proper overcurrent protection.
3. Ensure proper grounding according to electrical code requirements.
4. Check motor rotation direction before operating. The wheel should rotate down and toward the workpiece.

5.4 Coolant System Setup

1. Fill the coolant tank with water-soluble coolant mixed with rust inhibitor per the coolant manufacturer's recommendations.
2. Prime the recirculating pump by turning on the coolant system and verifying flow.
3. Adjust the dual flare nozzles to direct coolant flow to both sides of the cutting zone.
4. Set the flow control ball valve to the desired coolant volume.

5.5 Abrasive Wheel Installation

1. Disconnect power from the machine.
2. Verify the wheel is rated for at least 3,450 RPM and is designed for the material you will be cutting.
3. Install the wheel on the 5/8" LH spindle arbor.
4. Secure with the flange and arbor nut, tightening snugly with wrench only.
5. Reconnect power and verify proper wheel rotation.

6. Operation Instructions

6.1 Pre-Operation Checklist

- Inspect the abrasive wheel for damage, cracks, or excessive wear.
- Verify the wheel is properly secured and rated for 3,450 RPM.
- Check coolant level in the tank and top off if necessary.
- Verify coolant nozzles are properly aimed at the cutting zone.
- Ensure the work area is clean and free of obstructions.
- Put on required personal protective equipment.

6.2 Cutting Procedure

1. Position the material in the toolmakers vise, ensuring it is square to the wheel.
2. Secure the workpiece firmly in the vise.
3. Close the enclosure door.
4. Turn on the coolant system and verify flow to the cutting area.
5. Turn on the machine using the magnetic control push button.
6. Allow the wheel to reach full operating speed (3,450 RPM).
7. Lower the saw arm smoothly and steadily, applying consistent pressure.
8. Complete the cut and raise the saw arm to the full up position.
9. Turn off the machine and wait for the wheel to stop completely.
10. Turn off the coolant pump.
11. Open the enclosure door and remove the workpiece.

6.3 Cutting Tips for Best Results

- Use consistent, moderate feed pressure; let the wheel do the work.
- Ensure adequate coolant flow throughout the entire cut to minimize heat damage.
- Select the appropriate wheel type for your material.
- Support long materials adequately using the side access panel if needed.
- Allow the wheel to clear debris naturally; do not force cuts.
- For metallographic samples, use a slower feed rate to produce cleaner cut surfaces.

7. Maintenance

7.1 Daily Maintenance

- Clean metal shavings, dust, and debris from the cutting chamber after each use.
- Inspect the abrasive wheel for damage or wear.
- Check vise operation and tighten if necessary.
- Verify coolant level and condition; top off as needed.
- Use the wash down hose to clean the interior of the enclosure.

7.2 Weekly Maintenance

- Inspect V-belt for wear, cracks, or proper tension.
- Check all fasteners for tightness.
- Clean coolant nozzles to ensure unobstructed flow.
- Inspect the coolant tank for sediment buildup.

7.3 Monthly Maintenance

- Inspect bearings for noise or rough operation.
- Clean motor housing to prevent dust accumulation and overheating.
- Check wiring and electrical connections for wear or loose contacts.
- Verify motor mounting hardware is secure.
- Drain, clean, and refill the coolant tank with fresh coolant solution.
- Inspect and clean the recirculating pump and intake screen.

7.4 Wheel Replacement

Replace wheels when they show signs of wear (reduced diameter), visible damage, cracks, or chips. Follow the wheel installation procedure in Section 5.5.

8. Troubleshooting

Problem	Possible Cause / Solution
Motor will not start	Check power supply and connections; verify magnetic starter is engaged; replace switch if faulty
Excessive vibration	Check arbor nut tightness; replace damaged wheel; replace worn spindle bearings
Poor cut quality	Replace worn wheel; select appropriate wheel for material; reduce feed pressure; increase coolant flow
Wheel overheating	Reduce feed rate; increase coolant flow; verify nozzle aim; select wheel rated for material
Material slipping	Increase vise clamping pressure; replace worn vise jaws
Belt slippage	Replace worn V-belt; adjust belt tension
Coolant not flowing	Check pump operation; verify tank level; clean nozzles and intake screen; check flow control valve
Coolant leaking	Inspect door seals; check tank and hose connections; verify drain plug is secure
Internal light not working	Replace bulb; check wiring connections

9. Replacement Parts

Genuine Kalamazoo Industries replacement parts are kept in stock and shipped from Kalamazoo, Michigan. Using genuine parts ensures optimal machine performance and maintains warranty coverage.

9.1 Recommended Spare Parts

We recommend keeping the following parts on hand to minimize downtime:

Part Number	Description
292-047	Spindle with Tight Flange
292-008	Loose Flange
702-002	Spindle Assembly
710-052	Door Safety Interlocks (optional)

9.2 Ordering Parts

To order replacement parts, contact Kalamazoo Industries directly or visit the online parts store at www.kalamazooind.com. Have your machine model number (K10WBT) ready when ordering.

10. Warranty Information

10.1 Warranty Coverage

Parts warranty is guaranteed for one year from the original date of purchase by the original purchaser, covering defects in material or workmanship under normal use. This warranty covers the replacement of defective parts. Some exclusions may apply.

10.2 Warranty Exclusions

This warranty does not cover:

- Normal wear items including abrasive wheels, belts, and bearings
- Damage resulting from misuse, abuse, or improper maintenance
- Damage from cutting inappropriate materials
- Modifications or alterations to the machine
- Damage from improper electrical connection
- Coolant system damage due to use of non-recommended coolant

10.3 Return Authorization

Obtain written authorization before returning any merchandise by contacting Customer Service at (269) 382-2050. Unauthorized returns may not be accepted.

11. Contact Information

KALAMAZOO INDUSTRIES, INC. Kalamazoo, Michigan

Toll-Free: 1-800-592-2050
Local: (269) 382-2050
Website: www.kalamazooind.com
Office Hours: Monday – Friday, 8:00 AM – 4:30 PM EST


Online Resources

- Product Registration: www.kalamazooind.com/product-registration
- Parts Orders: www.kalamazooind.com/parts-by-category
- Technical Videos: www.kalamazooind.com/videos
- Contact Form: www.kalamazooind.com/contact-us

Thank you for choosing Kalamazoo Industries!

Made in the USA

INCOMING POWER CONNECTS
TO L1, 3L2, AND 5L3
ON SAW MOTOR CONTACTOR



KALAMAZOO INDUSTRIES INC.

DRAWN BY	DATE	DESCRIPTION
ASHLEY	07/14/16	KIOMBT SCHEMATIC
REVISED BY	DATE	PART #
MATERIAL		

Y

