Tips to having a good cut

Below are just some of many tips to having an improved cut.

- 1) Make sure to use an abrasive cutoff wheel is designed to be used with the material that you're looking to cut. (Every cutoff wheel is different there will be some experimenting).
- 2) Clamp on both sides of the material whenever possible. Reason is this would help minimize the burr.
- 3) Part placement. Make sure the part is at least ¼" from center.
- 4) If you're looking for metallurgical cut make sure you a grinding fluid coolant. Minimizes any burning.