



INCOMING LINE VOLTAGE  
CONNECTS TO 1L1 AND 3L2



SINGLE PHASE MOTOR  
DRIVE

SINGLE PHASE MOTOR  
VAC

MOTOR LEAD CONNECTION



INTERCHANGE #5 AND #8 LEADS  
TO REVERSE ROTATION

**KALAMAZOO INDUSTRIES INC.**

DRAWN BY	DATE	DESCRIPTION
ASHLEY	9/19/12	1 PH SCHEMATIC
REVISED BY	DATE	PART #
MATERIAL		

Y  
X