

## Why Your CNC Machine Is Waiting on You

Speed Up Material Prep with the K10B 10" Industrial Chop Saw

Your CNC machine can only run as fast as you can feed it. If material prep slows you down, your whole shop feels it. The K10B dry cut chop saw helps you cut stock fast so your machines stay busy.

### THE PROBLEM

Raw stock arrives in lengths that need cutting before machining. Slow material prep creates a bottleneck before CNC work even starts. Inconsistent cuts mean extra machining time to square up blanks. Waiting on outside cut services delays production schedules. Small shops simply can't afford dedicated cutting departments.



### THE K10B SOLUTION

The K10B packs a 3 HP motor spinning at 3,450 RPM. It slices through 1.5" solid steel and 2.5" pipe in seconds. The cam lock vise holds material tight for accurate, repeatable cuts every time. A heavy-duty cast iron base absorbs vibration for cleaner results. The compact footprint fits next to your CNC without eating floor space. Keep material prep in-house and control your own schedule.

#### K10B Quick Specs

**Motor:** 3 HP

**Speed:** 3,450 RPM

**Solid Capacity:** 1.5" steel

**Pipe Capacity:** 2.5" steel

**Wheel Size:** 10"

**Made in:** USA

**Ready to Speed Up Your Shop?**

Call 800-592-2050 or visit [kalamazooind.com](http://kalamazooind.com)